

	L #	Hits	Search Text	DBs	Time Stamp
1	L1	508954	repair\$4 reshape\$4 recoat\$4 restor\$4	USPA T; US-P GPUB ; EPO; JPO; DERW ENT; IBM TDB	2003/11/17 14:16
2	L2	478	1 and((427/528,529,530, 531,576,577).CCLS.) or ((204/192.16).CCLS.)	USPA T; US-P GPUB ; EPO; JPO; DERW ENT; IBM TDB	2003/11/17 14:21
3	L3	1369	1 and (((427/528,529,530,531,576,577).CCLS.) or ((204/192.16).CCLS.)) and(wear resistant erosion corrosion multilayer multi adj layer)) <u>or</u> (((427/528,529,530,531,576,577).CCLS.) or ((204/192.16).CCLS.)) and(Ti titanium Zr zirconium TiN ZrN TiB ZrB))	USPA T; US-P GPUB ; EPO; JPO; DERW ENT; IBM TDB	2003/11/17 14:18
4	L4	59	1 and (((427/528,529,530,531,576,577).CCLS.) or ((204/192.16).CCLS.)) and(wear resistant erosion corrosion multilayer multi adj layer)	USPA T; US-P GPUB ; EPO; JPO; DERW ENT; IBM TDB	2003/11/17 14:20

See L6
X

SN09/700,473

2

	L #	Hits	Search Text	DBs	Time Stamp
5	L5	48	1 and (((427/528,529,530,531,576,577).CCLS.) or ((204/192.16).CCLS.)) and(Ti titanium Zr zirconium TiN ZrN TiB ZrB)	USPA T; US-P GPUB ; EPO; JPO; DERW ENT; IBM TDB	2003/11/17 14:21
6	L6	70	4 or 5	USPA T; US-P GPUB ; EPO; JPO; DERW ENT; IBM TDB	2003/11/17 14:21
7	L7	2894	((427/528,529,530,531,576,577).CCLS.) or ((204/192.16).CCLS.)	USPA T; US-P GPUB ; EPO; JPO; DERW ENT; IBM TDB	2003/11/17 14:21
8	L8	451	7 and ((ion) with(mix mixing mixed implant\$4 implantation))	USPA T; US-P GPUB ; EPO; JPO; DERW ENT; IBM TDB	2003/11/17 14:32

3

	L #	Hits	Search Text	DBs	Time Stamp
9	L9	18	6 and ((ion) with(mix mixing mixed implant\$4 implantation))	USPA T; US-P GPUB ; EPO; JPO; DERW ENT; IBM TDB	2003/11/1 7 15:17
10	L10	414	reshap\$4 and((427/528,529,530, 531,576,577).CCLS.) or ((204/192.16).CCLS.)	USPA T; US-P GPUB ; EPO; JPO; DERW ENT; IBM TDB	2003/11/1 7 15:14
11	L11	301	10 and ((427/528,529,530,53 1,576,577).CCLS.) or ((204/192.16).CCLS.) and(wear resistant erosion corrosion multilayer multi adj layer)	USPA T; US-P GPUB ; EPO; JPO; DERW ENT; IBM TDB	2003/11/1 7 15:15
12	L12	251	10 and (((427/528,529,530,53 1,576,577).CCLS.) or ((204/192.16).CCLS.) and(Ti titanium Zr zirconium TiN ZrN TiB ZrB)	USPA T; US-P GPUB ; EPO; JPO; DERW ENT; IBM TDB	2003/11/1 7 15:15

77 Computer
will not show
these terms
highlighted

cannot properly review

highlighter was
on erroneous
- no apparent
reason for
omission!

U

	L #	Hits	Search Text	DBs	Time Stamp
13	L14	28	(13 and ((ion) with(mix mixing mixed implant\$4 implantation))) not 9	USPA T; US-P GPUB ; EPO; JPO; DERW ENT; IBM TDB	2003/11/1 7 15:18
14	L15	51	13 and (turbine blade)	USPA T; US-P GPUB ; EPO; JPO; DERW ENT; IBM TDB	2003/11/1 7 15:21
15	L18	6	16 or 17	USPA T; US-P GPUB ; EPO; JPO; DERW ENT; IBM TDB	2003/11/1 7 15:24
16	L16	3	13 and ((turbine blade)same (reshap\$4 repair\$4 reshape\$4 recoat\$4 restor\$4))	USPA T; US-P GPUB ; EPO; JPO; DERW ENT; IBM TDB	2003/11/1 7 15:54

5

	L #	Hits	Search Text	DBs	Time Stamp
17	L17	3	14 and (turbine blade)	USPA T; US-P GPUB ; EPO; JPO; DERW ENT; IBM TDB	2003/11/17 15:55
18	L10	414	reshap\$4 and((427/528,529,530, 531,576,577).CCLS.) or ((204/192.16).CCLS.)	USPA T; US-P GPUB ; EPO; JPO; DERW ENT; IBM TDB	2003/11/17 15:46
19	L19	14104	reshap\$4	USPA T; US-P GPUB ; EPO; JPO; DERW ENT; IBM TDB	2003/11/17 15:47
20	L20	3	19 and 10	USPA T; US-P GPUB ; EPO; JPO; DERW ENT; IBM TDB	2003/11/17 15:50

6

	L #	Hits	Search Text	DBs	Time Stamp
21	L21	3	6 and ((turbine blade) same (reshap\$4 repair\$4 reshape\$4 recoat\$4 restor\$4))	USPA T; US-P GPUB ; EPO; JPO; DERW ENT; IBM- TDB	2003/11/1 7 15:56
22	L22	13	6 and (turbine blade) not 21	USPA T; US-P GPUB ; EPO; JPO; DERW ENT; IBM- TDB	2003/11/1 7 15:57